

SAS Superstructure

Location: 04-SF-80-13.2 / 13.9 Client Name: CalTrans

Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 211 Const Calendar Day: 780 Date: 28-Oct-2011 Friday Inspector Name: Iranmanesh, Abbas Title: Transportation Engineer

Inspection Type: Continuous

Shift Hours: 07:00 am 03:30 pm Break: 00:30 Over Time:

Federal ID: Location:

Reviewer: Schmitt, Alex Approved Date: Status: Submit

Weather

Temperature7 AM50 - 6012 PM4PM60 - 74PrecipitationNoneConditionSunny

Working Day 🗸 If no, explain:

Diary:

Work description.

ABF Crews activities:

1- The crews continued working At Pier W2 with respect to some of the following submittals

- •ABF-SUB-002171R01, "PWS Restraint System at Pier W2".
- ABF-SUB-002283R00, "Cable Erection Plan-Secondary PWS Hauling System".
- •ABF-SUB-002019R02, "West End Tramway".
- •ABF-SUB-002416R00, "West Floating Arms".
- •ABF-SUB-002506R00, "Cable Erection Plan-W2 Transfer Arms".
- •ABF-SUB-002393R00, "Pier W2 Access Platform".
- •ABF-SUB-002447R01, "Erection Plan (Cable)-Main Cable Strand (PWS) Erection plan".

INSTALLATION:

- 1. The ABF crews continued their activities on the sliding the PWS into the deviation saddles as follows:

 •As mentioned in the previous diary, the construction of PWS on W-Line deviation saddle was completed from the beginning. It was observed that the existing tension force in the PWS is low and the wires are loose. The ABF plan to put the PWS under more tension force before sliding it inside the saddle slot. No action is taken on the sliding of the W-Line saddle inside the saddle slot.
- •As mentioned in the previous diary, the ABF crews continued sliding the PWS inside the E-Line saddle. It was checked that the PWS wires were loose for the portion of the saddle in which the PWS was already inside the slot. Some of the wires are flipped over the top of each other. This is another indication that tension force in the PWS is low. The crews continued the sliding process of the remaining PWS early in the morning. However, after inspection by the ABF, the work done was rejected and the crews have to start from the beginning of the North side of the E-line deviation saddle to construct the PWS cross section. The tension force in the PWS doesn't seem to be adequate unless more tension force is applied. Otherwise the result of the work will be the same.
- 2. The ABF Mechanic, Mr. Michael Ford check all the connections of the hydraulic jacking system and made the necessary adjustments. However, a few have leakage that after the shut off the system will be repaired.
- 3. The selected attached pictures show the detail of the performed activities.

ABF crews involved in the Secondary hauling system Hauling PWS and Positioning



Time 12:46 PM

04-0120F4

04-SF-80-13.2/13.9

Self-Anchored

Suspension Bridge

Run date 21-Nov-14

Daily Diary Report by Bid Item

ob Name:	04-0120F4	Inspec	tor Name	Iranmanesh,	Abbas	Di	ary #: 2	211 [Date: 28-Oct-2011	Friday	
Rigoverto -Waler He -Fleix Mel -Jose Tor -Michael I	ernandez Igar res										
04-0120F4	Bid Iten	n: 0 51	0-000-	000.051	ERECT ST	TRUCTL	IRAL ST	EEL (BF	RIDGE)		
AMERICAN E	RIDGE/FLUOF	R, A JV									
04-0120F4	Bid Iten	ո։ 060	E-W20	C-WDS.060	E Line W2	Cap We	est Devi	ation Sa	nddle		
AMERICAN E	BRIDGE/FLUOF	R, A JV									
Labor											
Trade	Cla		Name		RT Hrs	OT Hrs	DT Hrs	Total	Remarks		Dispute
Contractor:	AMERICAN	BRIDGE/F	LUOR, A JV								
Mechan			MICHAEL F		2.00	0.00	0.00	2.00			
Ironwork			JOSE TORR		8.00	0.00	0.00	8.00			
Ironwork			FELIX MELG		8.00	0.00	0.00	8.00			
Ironwork				RNANDEZ-ZEL		0.00	0.00	8.00			
Ironwork	ker JN	M	RIGOVERTO) GARCIA	8.00	0.00	0.00	8.00			
Equipment									Rental Company		
Equipm	ent ID Desc	ription			RT Hrs	OT Hrs	ST Hrs	IT Hrs	Remarks		Dispute
Contractor:	AMERICAN	BRIDGE/F	LUOR, A JV								
002154	Equip	oment, Cra	ne, 60 Ton						No		
					0.00	0.00	0.00	0.00			
04-0120F4	Bid Iten	n: 060	W-W20	C-WDS.060	W Line W2	2 Cap W	est Dev	iation Sa	addle		
	BRIDGE/FLUOF										
-WEIGOAIVE	JRIDGE/I EGGI	ν, Ασν									
04-0120F4	Bid Iten	n: 060	X-W2C	C-JKS.060	E-W Line	Cross O	ver W2	Cap Jac	king Saddle		
AMERICAN BRIDGE/FLUOR, A JV											
		, ,									

Attachment





Daily Diary Report by Bid Item

Job Name: 04-0120F4 Inspector Name Iranmanesh, Abbas Diary #: 211 Date: 28-Oct-2011 Friday





